Aquamatic East Coast Annual Preventative Maintenance Packages

Diagnostic service is not an annual preventative service. The fee for a diagnostic service is \$300.00. A diagnostic is required when a cover system is not operating properly & an annual service will not resolve the issue. It is also required when we cannot resolve the cover issues the same day due to needing to order parts If a diagnostic service is performed and our technicians are able to get the cover system operational, we will reduce the diagnostic service by \$200 and move forward with a preventative maintenance of your choice.

Special features are pool designs that are more labor intensive. These include vanishing edge pools, pools with a raised wall, pools with a lift lid, or a hidden leading edge bar, and pools that are over 800 sq. ft. and up to 1200 sq. ft. There will be an additional cost of \$125 for each above mentioned special feature.

| cuge sui) c | ina poolo inavaro over | ooo oqi iti aiia ab to ==oo oqi | | | and the international operator | |
|--|--|---|---|---|---|---|
| Service Options | Basic System Maintenance (BSM) | Basic System Maintenance including replacement parts (BSM w/parts) | Spa Complete System Maintenance (CSM Spa Only) | Complete System Maintenance (CSM) (minimum service requirement on Hidden Leading edge Bar Systems and Lift Lid Systems) | Complete System Maintenance including replacement parts (CSM w/parts) | Hydralux Package |
| Any service option is available; however, we recommend the following services for: | All cover systems electric or hydraulic *parts extra | All cover systems electric or hydraulic needing all new wear items **save on parts below** | Spa cover systems (Up to 100 sq. ft.) electric or hydraulic *parts extra | All cover systems electric or hydraulic (especially salt water pools) near trees and leaves *parts extra | All cover systems electric or hydraulic (especially salt water pools) needing all new wear items **save on parts below** | For Hydralux pool cover systems only *parts extra |
| Price | \$450 plus zone charge | \$858 plus zone charge *tax may vary* | \$500 plus zone charge | \$675 plus zone charge | \$1083 plus zone charge *tax may vary* | Call for Pricing plus zone charge |
| | Includes | Includes | Includes | Includes | Includes | Includes |
| Lubricate Working Parts, Pulleys, and Grease Fittings | • | • | • | • | • | • |
| Fine Tune Mechanism | • | • | • | • | • | • |
| Flush Out Tracks | • | • | • | • | • | |
| Inspect Sliders | • | • | • | • | • | |
| Inspect Guide Feeds | • | • | • | • | • | |
| Rope, Skew, Clutch Adjustments As Needed | • | • | • | • | • | |
| Inspect Hydraulic Fluid and Top Off Hydraulic Fluid As Needed | • | • | • | • | • | • |
| Clean Out Cover Box | • | • | • | • | • | |
| *Replace Sliders | | • | | | • | |
| *Replace Guide Feeds | | • | | | • | |
| *Replace All Pulleys | | • | | | • | |
| Scrub Cover With Approved Cleaner | | | • | • | • | |
| Wash Cover, mechanism, brackets, drum, castings & flange of salts and corrosion. Drain inspection during this process. | | | • | • | • | |
| Scrub & Power Wash Cover Slats | | | | | | • |